


STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
1594 West North Temple Suite 1210  
PO Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/96 To (mo./yr.) 12-31-96
  2. DOGM File Number (Mine No): 5 1013 1001
  3. Mine Name: Wesco
  4. Mineral(s) Mined (or permitted to mine): Sandstone
  5. Type of mine ☒ Surface Mine or ☐ Underground Mine
  6. Legal Description (Location of Lands Affected):  
SE 1/4, SW 1/4, Section 35, Township 11S, Range 10E.  
SW 1/4, SW 1/4, Section 30, Township 11S, Range 10E.  
\_\_\_\_ 1/4, \_\_\_\_ 1/4, Section \_\_\_\_\_, Township \_\_\_\_\_, Range \_\_\_\_\_
  7. Name of Operator or Company: Quality Stone
  8. Permanent Street Address: 8809 S. 700W.  
City, State, Zip: Sandy, Utah 84070  
Phone: (801) 255-2911
  9. Company Representative (or designated operator):  
Name: Wes Hansen  
Title: Manager  
Business Address: 8809 S. 700W.  
City, State, Zip: Sandy, Utah 84070  
Phone: (801) 255-2911
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 101.22 tons

3. How much **additional acreage** was disturbed during the past year? None
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.  
no additional disturbance - work conducted  
in prior workings
5. How much acreage was reclaimed during the past year? None
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
None
7. What is the total disturbed acreage at years end? 1 1/2 acre
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
The Quarry will continue to be worked and any  
portion that is no longer needed for continued  
operation will be reclaimed.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Title of Operator:

Signature of Operator:

Date:

Wes Hansen  
Manager  
*Wes Hansen*  
3/20/97